

Oil Field Environmental Incident Summary

Incident: 20140717164356 **Date/Time of Notice:** 07/17/2014 16:43

Responsible Party: RIM OPERATING, INC.

Well Operator: RIM OPERATING, INC.

Well Name: HMU 9-34XHR

Field Name: HOFFLUND

Well File #: 7594

Date Incident: 7/15/2014

Time Incident: 12:00

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 95

Sec: 9

Qtr:

Location Description:

Submitted By: Troy Johnson

Received By:

Contact Person: Jason Rouse
5 INVERNESS DRIVE EAST
ENGLEWOOD, CO 80112

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	40	Barrels	39.5	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Not Applicable. Spill was contained in the dike area and the standing fluid was recovered right away

Areal Extent:

Potential Environmental Impacts:

Not Applicable. Spill was contained in the dike area and the standing fluid was recovered right away

Action Taken or Planned:

Moved the oil that was in the tank to another tank on location. Recovered the standing fluid with a pump that was already on location. Had a clean up crew out to wash and suck up the affected area early the next morning. Tank will be steamed cleaned, inspected and then repaired or replaced.

Wastes Disposal Location: Recovered fluids were put in a tank on the location.

Agencies Involved: Caitlin Simpkins with NDIC was notified Wednesday morning 7/16/14. Caitlin passed the information on to Tamara Cook with NDIC. I visited with Tamara about the incident on the phone today.

Updates

Date: 7/18/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location within the diking according to the report. NDIC retains oversight.